## HISTORIC PROPERTY INVENTORY FORM

INDENTIFICATION SECTION Field Site No. OAHP No. Date Recorded 21 Feb 1995 Patrol Headquarters/Operations Change House Revised 17 July 1997 Site Name Historic Common **Documentation Services Office Building** Field Recorder I.C. Lindsay, W.S. White Owner's Name U.S. Department of Energy, Richland Operations Office P.O. Box 550 Address Richland, WA 99352 City/State/Zip Code HCRI Status Photography Roll 184, frames 9-13 x Survey/Inventory Photography Neg. No. Roll 270, frames 17-18 National Register (Roll No. & Frame No.) Roll 272, frames 18-20 State Register View of All exterior facades 21 Feb 1995 and 23 June 1997 Determined Eligible Date Determined Not Eligible Other (HABS, HAER, NHL) Photo at right: Roll 270, frame 14 Local Designation View of north and east facades District x Building Classification Site Structure Object x NR SR LR INV **Distric Status** Contributing Х Non-Contributing District/Thematic Nomination Name Hanford Site Manhattan Project and Cold War Era Historic District **Description Section** Materials & Features/Structural Types Roof Type x Gable **Building Type** Industry Modified Rectangular Flat Pyramidal Plan Structural System Wood Frame Monitor Other (specify) No. of Stories One Gambrel Shed Cladding (Exterior Wall Surfaces) Log **Roof Material** Horizontal Wood Siding Wood Shingle Rustic/Drop Wood Shake Clapboard Composition Wood Shingle Slate Board and Batten Tar/Built-up Vertical Board Tile x Asbestos/Asphalt (Transite Shingles) Metal (specify) Brick Other (specify) Stone Not visible Stucco Terra Cotta Foundation Concrete/Concrete Block Concrete Log Vinyl/Aluminum Siding Post & Pier Block Metal (specify) Stone Poured Other (specify) Brick Other (specify) Not visible (Include detailed description in Integrity **Description of Physical Appearance)** Intact Moderate Extensive Changes to plan Х Х Changes to windows Changes to original cladding Х Changes to interior Х Other (specify)

State of Washington, Department of Community Development
Office of Archaeology and Historic Preservation
111 21st Avenue Southwest Post Office Box 48343

111 21st Avenue Southwest, Post Office Box 48343 Olympia, Washington 98504-8343 (206)753-4011

#### LOCATION SECTION

Gable Front and Wing

Side Gable

Address	Building 3707-D, 300 Area					
City/Town/County/Zip Code		Richland/Benton County/99352				
Twp. 10 N Range 28 E	Section	11 <b>I/4 S</b> e	ction NW	1/4 1/4 Sec		
Tax No./Parcel No.			-	Acreage		
Quadrangle or map name		Richland, Washington Quad 7.5 min series, 1986				
UTM References Zone	11	Easting	324460	Northing	5137860	
Plat/Block/Lot			325310		5137820	
Supplemental Map(s)			325550		5136690	
			324440		5136720	



gh Styles/Forms (Check one or mo Greek Revival	Spanish Colonial Revival/Mediterranean
Gothic Revival	Tudor Revival
Italianate	Craftsman/Arts & Crafts
Second Empire	Bungalow
Romanesque Revival	Prairie Style
Stick Style	Art Deco/Art Moderne
Queen Anne	Rustic Style
Shingle Style	International Style
Colonial Revival	Northwest Style
Beaux Arts/Neoclassical	Commercial Vernacular
Chicago/Commercial Style	Residential Vernacular (see below)
American Foursquare	x Other (specify)
Mission Revival	Industrial Vernacular
<del>_</del>	
ernacular House Types	
Gable Front	Cross Gable

Pyramidal/Hipped

Other (specify)

#### NARRATIVE SECTION

Study Unit Themes (check one or more of the following	g)	
Agriculture Architecture/Landscape Architecture Arts Commerce Communications Community Planning/Development	Conservation  Education  Entertainment/Recreation  Ethnic Heritage (specify)  Health/Medicine  Manufacturing/Industry  Military	Politics/Government/Law Religion Science & Engineering Social Movements/Organizations Transportation X Other (specify) Manhattan Project/Cold War Eras X Study Unit Sub-Theme(s) General Site, Administrative Support;
Statement of Significance		Site Security
Date of Construction 1953  x In the opinion of the surveyor, this property appears to	Architect/Engineer/Builder  meet the criteria of the National Register of Historic Places.	

The 3707-D Building was originally built as a Hanford Patrol headquarters as well as a change house for workers in the northern portion of the 300 Area, specifically those in the 313 and 333 fuel fabrication facilities. Due to additional security measures used to control access to fuel fabrication activities in the northern portion of the 300 Area, personnel with clearance to enter this area passed through a checkpoint in the southwest portion of the 3707-D Building. The building was constructed around the concrete 303-D Building, which was converted for use as a men's change room. Originally, much of the 3707-D Building was built to house men's and women's change rooms. The women's change rooms, however, were rarely used since the worker's union did not allow women into the fuel fabrication workforce until the late 1950s. The men's change rooms were used only slightly more, as the 313 and 333 Buildings also had change rooms. Therefore, in 1966 the interior of the building was overhauled and the men's change room facilities on the east side of the building were converted to office space. Later, in the 1970s, the women's change facilities were converted to drawing control rooms and a lunch room, and the 303-D Building (located in the center of 3707-D) was converted for use as a vault where records and drawings were archived. The Hanford Patrol headquarters in the southwest portion of the building was also converted to office space, and the large original lunch room in the northwest portion of the building was converted to a drawing control room. Since that time, the offices against the east wall have undergone only minor structural adjustments. Portions of the 3707-D Building were intermittently used for document control throughout its history and continue in that capacity today. As a security facility, change house, document control repository, and office building, the 3707-D Building has served a significant supporting role for a number of 300 Area missions. It is therefore the conclusion of the U.S. Departmen

### **Description of Physical Appearance**

x In the opinion of the surveyor, this property is located in a potential historic district (National and/or local).

The 3707-D Building is a wood frame, modified rectangular building measuring 115 feet by 76 feet on an east-west axis. The facility has asbestos shake siding and a shallow gable roof with built-up tar and gravel surfacing. The exterior of the building has remained largely unchanged except for the removal and addition of doors at the northeast corner of the building to meet the access needs of the renovated interior. Originally there were two doors side-by-side on the east edge of the north elevation of the building leading to a former contaminated change room in the northeast corner, but the doorways have since been removed and sided over with asbestos shakes. Currently on the north elevation, there are three single doors. A sliding metal door near the center of the elevation is still present but was sealed shut during one of the building's interior renovations. An overhang shelters the sliding door and one of the single entry doors. On the opposite edge of the north elevation is an entry vestibule that projects to the north. On its north end is a double pane, sliding window. Access to the vestibule and the interior of the building is through a recessed wood door on the west side of the vestibule. Most of the remainder of the west elevation consists of a lone row of eight horizontal, screened windows separated by wood framing. A cement walkway runs along the building below the windows. An overhang shelters most of the wall except for the south end, which protrudes five feet out to the edge of the overhang. The southwest corner of the building was originally used by the Hanford Patrol as a security checkpoint. The area south of the building was fenced so that workers had to walk through doors on the north and south ends of the southwest portion of the building that extends to the west. Another row of three windows with wood framing is located on the west side of this extension. Two doorways on the southwest portion of the dold checkpoint area in the southwest corner of the building, though one of the doors has b

Inside the building, there are asbestos tile floors and a drop ceiling. The original walls are concrete block, and the office walls added during renovations are standard Hauserman partitions. The office doors are wood with metal framing. The southern and eastern portion of the building provides 15 offices for Hanford contractor engineers as well as space for document storage. A maintenance equipment room, lunch room, and conference room are also located in the building.

# HISTORIC PROPERTY INVENTORY FORM Building 3707-D (Continuation Sheet 1 of 1)

#### Major Bibliographic References

Drawings H-3-8025, H-3-8026, H-3-31879, H-3-35264, H-3-44841.

Trahan, Nelson (DynCorp Tri-Cities Services facilities manager). 17 July 1997. Personal Communication. Richland, Washington.

Westinghouse Hanford Company. 1993. Condition Assessment Survey, 3707-D Narrative. Richland, Washington.

Westinghouse Hanford Company. 1993. 300 Area Building Catalog. Richland, Washington.

Weakley, Everett (retired Hanford employee). 17 July 1997. Personal Communication. Richland, Washington.